



WARRENTON-FAUQUIER - W66

Coordinates: 38°35'20"N - 77°42'44"W

Elevation: 329'

Traffic Pattern: Left

Runway: 14-32/4103' x 60' (Asphalt)
Available runway length will vary in 2004 due to construction (check NOTAMs)

Runway Lights: MIRL

Lighting may not be available due to construction in 2004 (check NOTAMs)

Rotating Beacon: Yes

Sectional Chart: Washington

Location: 12 miles Southeast of Warrenton

Fuel: 100LL

Maintenance: AF & PP; IA

Manager: Michael P. Anderson, (540) 788-4323

Airport Telephone: (540) 788-4323

Operators: Skyworld Aviation, Inc.,
P. O. Box 147, Midland, VA 22728, (540) 788-9380; Andrews, P. O. Box 182,
Midland, VA 22728; Warrenton Fauquier
Flight Center, P. O. Box 68, Midland, VA 22728

Hours of Operation: 0800-1730

Remarks: Rwy 6-24 Closed; Caution: Deer and Wild Turkeys Rwy 14/32, Attended daytime, Flight Instruction, Charter, Aircraft Sales, Aerobatic Box, Rental Cars, Crew Car, Restrooms, Catering, Snacks, Taxi, Food & Lodging nearby

Points of Interest: John Marshall's Birthplace, Thoroughbred Horse Farms, Flying Circus Aerodrome, Skyline Drive, Old Town Warrenton, Little Washington Inn (5 star), Black Horse Inn, Kelly's Ford Inn, Oasis Inn, Wine Country

Published Instrument Approach: Yes

AWOS III: No

WeatherMation: No, but Duats is available.

COMMUNICATIONS: CTAF/UNICOM 122.7, GCO 135.075

NAVIGATION AIDS: Casanova VORTAC
116.3 119° 7.9 NM

APPROACH LIGHTING: Rwy 14 & Rwy 32
APAP; Rwy 14 APAP may not be available during construction in 2004

WARRENTON